NOTICE TO MARINERS



No. 40 of 2018

'LEAC BUIDHE' BUOY

Mariners are advised that a Port Lateral Mark has been deployed marking 'Leac Buidhe' Rock in the following position 53°16.650'N 006°05.100'W. The buoy has the following light characteristic FI(4)R.6s.

The buoy will be seasonally deployed from April to October.



